

February 4, 2021

Lake Avondale Stormwater Project - Poor Condition Tree Photos



Tree 13 - Dieback in lower trunk



Tree 18 - Low split into two codominant leaders; extensive dieback in canopy



Tree 68 - Dieback in canopy




Tree 84 - Several trunks wounds with decay



Tree 110 - Trunk wound with decay



Tree 116 - Trunk wound covering 70% of diameter



Tree 204 - Damage and dieback in canopy



Tree 214 - Cavity in lower trunk



Tree 236 - Cavity and decay in trunk



Tree 317 - Dieback in canopy



Tree 352 - Cavity throughout trunk



Tree 363 - Dieback in canopy



Tree 379 - Cavity in upper trunk



Tree 383 - Dieback in canopy



Tree 383 - Multi stem; decay in base